



ST 5051

USA MAP LARGE


APPLICATION INSTRUCTIONS

SIZE



approx. 23 feet 5 inches wide x
16 feet long




PAINTERS & TIME

4-5 painters for 3-4 hrs







INCLUDED IN THE BOX: 15 Stencil Sheets
(see other stencil sheets on the next few pages)






GULF OF MEXICO




BEFORE YOU START PAINTING: Please completely read the General Instructions & prepare your surfaces as recommended.



STEP 1:


Separate your **STENCIL** pieces along the perforations and set them aside.

Align your **STENCIL** pieces edge to edge to create the map, as shown, in your desired location.




STEP 2:

Paint the outlines of your **STENCIL** pieces to create the border of the map. **DO NOT PAINT THE STARS YET.** Repeat 1-2 more times to achieve desired vividness, drying after each application. Then remove your **STENCIL** pieces.



STEP 3:


Align the **STENCIL O & L** map pieces over the painted pavement. Paint the outlines. **DO NOT PAINT THE STARS YET.** Repeat 1-2 more times to achieve desired vividness, drying after each application. Then remove your **STENCIL** pieces.



STEP 4:

Fill in the gaps so your **STENCIL** is complete.


*****TIP:** You can use the 9 in rectangles to help you fill in the gaps.



STEP 5: PAINT THE INSIDE


Now paint the inside shapes of the USA Map. Your painted USA Map should look like the image to the left. Repeat 1-2 more times to achieve desired vividness, drying after each application.

Before proceeding to the next step, make sure the paint on the pavement is completely dry.



STEP 6: PAINT THE STARS


Align your **STENCIL** pieces over the painted borders, as shown, and paint the stars (state capitals). Then remove your **STENCIL** pieces.



STEP 7:

Make sure every state has a star (state capitals).

*****TIP:** The extra **STENCIL** pieces have stars you can use to fill in the missing state capitals.



STEP 8: PAINT HAWAII & ALASKA

After you place Hawaii and Alaska in the correct spot on the map. Paint Hawaii and Alaska. Repeat 1-2 more times to achieve desired vividness, drying after each application. Then Remove your **STENCILS**. Fill in the gaps so your **STENCILS** are complete.


Lastly, paint the star (state capital) of each state.

Allow the paint to dry for a minimum of 24 hours before use.

CONGRATULATIONS!!!

**YOU FINISHED PAINTING USA MAP LARGE
YOU DID IT! GIVE YOURSELVES A PAT ON THE BACK!**

Your finished USA Map Large should look like the image below.



Have any questions? We're here to help – call us at (800) 681-0684!

VISIT OUR WEBSITE AT WWW.FITANDFUNPLAYSCAPES.COM

THIS INFORMATION IS COPYRIGHT MATERIAL. ALL RIGHTS ARE RESERVED. © 2022 FIT AND FUN PLAYSCAPES, LLC.