

ST 5125 - CANADA MAP APPLICATION INSTRUCTIONS



SIZE


approx. 14 feet wide by 12 feet tall

PAINTERS & TIME

3-4 painters for 4-5 hrs

INCLUDED IN THE BOX:

5 Stencil Sheets



BEFORE YOU START PAINTING:
Please completely read the General Instructions
& prepare your surfaces as recommended.



Place down STENCIL A.



STEP 2


Paint the borders and bodies of water labels of the map. **DO NOT PAINT THE STARS OR PROVINCE LABELS YET**.

Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL A.



STEP 3

Place down STENCIL B, using the guides to align it with the painted section of the map.




STEP 4

Paint the borders of the map. **DO NOT PAINT THE STARS OR PROVINCE LABELS YET**. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL B.



Place down STENCIL C, using the guides to align it with the painted section of the map.



STEP 6

Paint the borders and bodies of water labels of the map. **DO NOT PAINT THE STARS OR PROVINCE LABELS YET**. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL C.



STEP 7

Place down STENCIL D, using the guides to align it with the painted section of the map.




STEP8

Paint the borders and bodies of water labels of the map. **DO NOT PAINT THE STARS OR PROVINCE LABELS YET**. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL D.



Punch out the circle shape that contains the star from STENCIL E and set aside. Place down STENCIL E, using the guides to align it with the painted section of the map.



STEP 10

Paint the borders and bodies of water labels of the map. **DO NOT PAINT THE STARS OR PROVINCE LABELS YET**. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL E.



STEP 11

Place down STENCIL F, using the guides to align it with the painted section of the map.



STEP 12

Paint the borders and bodies of water labels of the map. **DO NOT PAINT THE STARS OR PROVINCE LABELS YET**. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL F.



Fill-in the bridges to make the borders complete.

TIP: You can use the enclosed bridge tools to help fill-in the gaps.



STEP 14

Punch out the island containing the capital from STENCIL A and set aside. Align STENCIL A to the painted surface. Paint the punched-out island shape and the other island above it. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL A.



STEP 15

Punch out the island containing the capital along with the shapes containg province labels from STENCIL D and set aside. Align STENCIL D to the painted surface. Paint the punched-out island shapes, the punched-out island, and the other island just above. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL D.



STEP 16

Align STENCIL F to the painted surface. Paint the islands. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL F.



Paint the inside shapes of the map. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Before preceding to the next step, make sure the paint on the surface is completely dry.



STEP 18

Align STENCIL A to the painted surface. Paint the stars (capitals) and province labels. Align the punched-out island back in place and paint the star as well. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL A.



STEP 19

Align STENCIL B to the painted surface. Paint the stars (capitals) and province labels. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL B.



STEP 20

Align STENCIL C to the painted surface. Paint the stars (capitals) and province labels. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL C.



Align STENCIL D to the painted surface. Paint the stars (capitals) and province labels. Align the punched-out island and shapes containing the province labels back in place and paint the star and province labels as well. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL C.




STEP 22

Align STENCIL E to the painted surface. Paint the stars (capitals). Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Remove STENCIL E.

CONGRATULATIONS!

YOU FINISHED PAINTING "MOKO JUMBIE"!
Your finished painting should look like the image below.



Have any questions?

We're here to help – call us at (800) 681-0684! Visit our website: FITANDFUNPLAYSCAPES.COM